

Vehicle Condition Report

Brasher's Portland Auto Auction

23585 NE Sandy Blvd.
Wood Village, OR 97060
(503) 492-9200

All listings are subject to change without notice. Information is deemed to be reliable, but not guaranteed until announced on the auction block.

Vehicle Description

2008 Chevrolet G2500 Vans Gas Wagon Express

| | | | |
|--------------|----------------------------|----------|-------|
| VIN | 1GAGG25K381200174 | | |
| Ext. Color | White | | |
| Int. Color | Gray | Interior | Cloth |
| Mileage | 21,118 Actual Miles | | |
| Engine | 6.0L 8-Cylinder Gas | | |
| Transmission | Automatic | | |



Auction Data

| | | | |
|-----------|--|-------|------|
| Sale Date | Mon - Feb 8 - Open to the Public | | |
| Run # | W022 | Inv # | 7840 |
| Consignor | GSA FLEET SERVICES | | |


Declarations

| | |
|----------|-----------------------------------|
| Warranty | GSA Regular Terms |
| Mileage | 21,118 Actual Miles |
| Title | Clear Title |

Equipment

- 2 Wheel Drive
- Trip Counter
- Steel Wheels
- Power Steering
- Automatic Transmission
- Rear Barn Doors
- AM/FM CD
- Power Brakes
- 8 Cylinder Gas
- Dual Air Bag
- Hard Top
- Air Conditioning
- Tilt Steering Wheel
- Tinted Windows

Damage Descriptions (CR completed on 1/7/2016 by Ryan Heath)

| # | Location | Damage Action | Severity | Parts \$ | Other \$ | Repair hours | Paint hours | Part hours | Total |
|--|-------------------|--------------------|-------------|----------|----------|--------------|-------------|------------|-------|
| Front | | | | | | | | | |
|  | 1 Front Bumper | Dents W/ Paint Dmg | > 12 Inches | | | | | | -- |
| Front Subtotal | | | | -- | -- | -- | -- | -- | -- |
| | | | | | | -- | -- | -- | -- |
| Left | | | | | | | | | |
| | 2 Left Front Door | Multiple Scratches | 3 | | | | | | -- |
| Left Subtotal | | | | -- | -- | -- | -- | -- | -- |
| | | | | | | -- | -- | -- | -- |

2008 Chevrolet G2500 Vans Gas Wagon Express

VIN: 1GAGG25K381200174 Inv#: 7840

| # | Location | Damage Action | Severity | Parts \$ | Other \$ | Repair hours | Paint hours | Part hours | Total |
|---|----------|---------------|----------|----------|----------|--------------|-------------|------------|-------|
|---|----------|---------------|----------|----------|----------|--------------|-------------|------------|-------|

Rear

| | | | | | | | | | |
|---|-------------|--------------------|------------|--|--|--|--|--|----|
| 3 | Deck Lid | Chipped | 10 Or More | | | | | | -- |
| 4 | Rear Bumper | Multiple Scratches | 10 Or More | | | | | | -- |

| | | | | | | |
|---------------|----|----|----|----|----|----|
| Rear Subtotal | -- | -- | -- | -- | -- | -- |
| | | | -- | -- | -- | -- |

Right

| | | | | | | | | | |
|---|------------------|--------------------|---|--|--|--|--|--|----|
| 5 | Right Front Door | Multiple Scratches | 3 | | | | | | -- |
|---|------------------|--------------------|---|--|--|--|--|--|----|

| | | | | | | |
|----------------|----|----|----|----|----|----|
| Right Subtotal | -- | -- | -- | -- | -- | -- |
| | | | -- | -- | -- | -- |

| | | | | | | |
|-------|----|----|----|----|----|----|
| Total | -- | -- | -- | -- | -- | -- |
| | | | -- | -- | -- | -- |

Tires

| Region | Brand | Size | Tread Depth |
|-------------|---------|------|-------------------|
| Left Front | MATCHED | /- | Average (Average) |
| Left Rear | MATCHED | /- | Average (Average) |
| Right Front | MATCHED | /- | Average (Average) |
| Right Rear | MATCHED | /- | Average (Average) |

Miscellaneous

| | |
|--------------------------|----|
| Coolant level | OK |
| Interior odor | OK |
| Oil level | OK |
| Transmission fluid level | OK |

2008 Chevrolet G2500 Vans Gas Wagon Express

VIN: 1GAGG25K381200174

Inv#: 7840

Images

